

OSHA Citation Tracking  
Serious Violations FY 2002

Installation	UIC	Inspection Date	Inspection Type	Violation Type	Standard Cited	Description	NAVOSH Reference	Abatement Date	Maximum Private Sector Penalty
Public Works Center - Pier 7, San Diego, CA	63387	12/13/2001	Pre-planned	Serious	1915.73(e)	<b>Fall protection</b> - When employees are working near the unguarded edges of decks of vessels afloat, they shall be protected by personal flotation devices, meeting the requirements of §1915.154(a).	OPNAVINST 5100.23F Chapter 11 Basic Requirements	2/1/2002	\$7,000
Puget Sound Naval Shipyard, PSNS, Bremerton, WA	00251	3/7/2002	Complaint	Serious	1910.23(c)(1)	<b>Guarding floor &amp; wall openings</b> - There is equipment with which falling materials could create a hazard.	OPNAVINST 5100.23F Chapter 11 Basic Requirements	7/19/2002	\$7,000
Puget Sound Naval Shipyard, PSNS, Bremerton, WA	00251	3/7/2002	Complaint	Serious	1910.179(g)(6)	<b>Overhead &amp; gantry cranes</b> -Runway conductors. Conductors of the open type mounted on the crane runway beams or overhead shall be so located or so guarded that persons entering or leaving the cab or crane footwalk normally could not come into contact with them.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 31 Responsibilities	8/13/2002	\$7,000
Puget Sound Naval Shipyard, PSNS, Bremerton, WA	00251	3/21/2002	Complaint	Serious	1910.134(g)(1)(i)A	<b>Respiratory protection</b> -The employer shall not permit respirators with tight-fitting facepieces to be worn by employees who have:Facial hair that comes between the sealing surface of the facepiece and the face or that interferes with valve function.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 15 (1503e)	8/9/2002	\$7,000
Puget Sound Naval Shipyard, PSNS, Bremerton, WA	00251	3/21/2002	Complaint	Serious	1910.1027(e)(2)	<b>Cadmium</b> -Demarcation. Regulated areas shall be demarcated from the rest of the workplace in any manner that adequately establishes and alerts employees of the boundaries of the regulated area.	OPNAVINST 5100.23F Chapter 11 Basic Requirements	8/9/2002	\$7,000
					1910.1018(f)(2)	<b>Inorganic Arsenic</b> -Demarcation. Regulated areas shall be demarcated and segregated from the rest of the workplace in any manner that minimizes the number of persons who will be exposed to inorganic arsenic.	OPNAVINST 5100.23F Chapter 11 Basic Requirements	8/9/2002	\$7,000

OSHA Citation Tracking  
Serious Violations FY 2002

Installation	UIC	Inspection Date	Inspection Type	Violation Type	Standard Cited	Description	NAVOSH Reference	Abatement Date	Maximum Private Sector Penalty
Puget Sound Naval Shipyard, PSNS, Bremerton, WA	00251	3/21/2002	Complaint	Serious	1910.1027(e)(3)	<b>Cadmium-</b> Access to regulated areas shall be limited to authorized persons.	OPNAVINST 5100.23F Chapter 11 Basic Requirements	8/9/2002	\$7,000
Puget Sound Naval Shipyard, PSNS, Bremerton, WA	00251	3/21/2002	Complaint	Serious	1910.1018(f)(3)	<b>Inorganic Arsenic-</b> Access to regulated areas shall be limited to authorized persons or to persons otherwise authorized by the Act or regulations issued pursuant thereto to enter such areas.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 5 Prevention and Control of Workplace Hazards	8/25/2002	\$7,000
Puget Sound Naval Shipyard, PSNS, Bremerton, WA	00251	3/21/2002	Complaint	Serious	1910.1027(e)(4)	<b>Cadmium-</b> Provision of respirators. Each person entering a regulated area shall be supplied with and required to use a respirator, selected in accordance with paragraph (g)(2) of this section.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 5 Prevention and Control of Workplace Hazards	8/25/2002	\$7,000
Puget Sound Naval Shipyard, PSNS, Bremerton, WA	00251	3/21/2002	Complaint	Serious	1910.1018(f)(4)	<b>Inorganic Arsenic-</b> Provision of respirators. All persons entering a regulated area shall be supplied with a respirator, selected in accordance with paragraph (h)(2) of this section.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 5 Prevention and Control of Workplace Hazards	8/25/2002	\$7,000

OSHA Citation Tracking  
Serious Violations FY 2002

Installation	UIC	Inspection Date	Inspection Type	Violation Type	Standard Cited	Description	NAVOSH Reference	Abatement Date	Maximum Private Sector Penalty
Naval Public Works Center, Great Lakes, IL	65113	3/25/2002	Complaint	Serious	1926.62(d)(1)(i)	<b>Lead exposure assessment</b> -General. Each employer who has a workplace or operation covered by this standard shall initially determine if any employee may be exposed to lead at or above the action level.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 21 Lead	5/2/2002	\$7,000
Naval Public Works Center, Great Lakes, IL	65113	3/25/2002	Complaint	Serious	1926.62(d)(2)(v)A	<b>Lead</b> -Until the employer performs an employee exposure assessment and determines actual employee exposure, the employer shall provide employees appropriate respiratory protection.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 21 Lead	5/2/2002	\$7,000
Naval Public Works Center, Great Lakes, IL	65113	3/25/2002	Complaint	Serious	1926.62(h)(4)	<b>Lead</b> - Where vacuuming methods are selected, the vacuums shall be equipped with HEPA filters and used and emptied in a manner which minimizes the reentry of lead into the workplace.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 21 Lead	5/2/2002	\$7,000
Naval Air Station Carswell JOI, Fort Worth,TX	83447	4/30/2002	Complaint	Serious	1960.8(a)	<b>Agency responsibilities</b> -The head of each agency shall furnish to each employee employment and a place of employment which are free from recognized hazards that are causing or are likely to cause death or serious physical harm.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 5 Prevention and Control of Workplace Hazards	6/27/2002	\$7,000
Department of the Navy, Naval Base V, San Nicholas Island, Point Mugu, CA	63410	5/21/2002	Complaint	Serious	1910.141(a)(5)	<b>Sanitation</b> -Vermin control. Every enclosed workplace shall be so constructed, equipped, and maintained, so far as reasonably practicable, as to prevent the entrance or harborage of rodents, insects, and other vermin. A continuing and effective extermination program shall be instituted where their presence is detected.	OPNAVINST 5100.23F Chapter 11 Basic Requirements, Chapter 5 Prevention and Control of Workplace Hazards	9/11/2002	\$7,000

OSHA Citation Tracking  
Serious Violations FY 2002

Installation	UIC	Inspection Date	Inspection Type	Violation Type	Standard Cited	Description	NAVOSH Reference	Abatement Date	Maximum Private Sector Penalty
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(e)(1)	<b>Asbestos</b> - Regulated areas --All Class I, II and III asbestos work shall be conducted within regulated areas. All other operations covered by this standard shall be conducted within a regulated area where airborne concentrations of asbestos exceed, or there is a reasonable possibility they may exceed a PEL.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(g)(1)(i)	<b>Asbestos regulated areas</b> --All Class I, II and III asbestos work shall be conducted within regulated areas. All other operations covered by this standard shall be conducted within a regulated area where airborne concentrations of asbestos exceed, or there is a reasonable possibility they may exceed a PEL. Regulated areas shall comply with the requirements of paragraphs (2), (3),(4) and (5) of this section.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(g)(1)(ii)	<b>Asbestos</b> - Wet methods, or wetting agents, to control employee exposures during asbestos handling, mixing, removal, cutting, application, and cleanup, except where employers demonstrate that the use of wet methods is infeasible due to for example, the creation of electrical hazards, equipment malfunction, and, in roofing, except as provide in paragraph (g)(8)(ii) of this section.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(g)(3)(iii)	<b>Asbestos</b> - Prompt clean-up and disposal of wastes and debris contaminated with asbestos in leak-tight containers except in roofing operations, where the procedures specified in paragraph (g)(8)(ii) of this section apply.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000

OSHA Citation Tracking  
Serious Violations FY 2002

Installation	UIC	Inspection Date	Inspection Type	Violation Type	Standard Cited	Description	NAVOSH Reference	Abatement Date	Maximum Private Sector Penalty
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(g)(4)(i)	<b>Asbestos</b> - Dry sweeping, shoveling or other dry clean-up of dust and debris containing ACM and PACM.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(g)(4)(ii)	<b>Asbestos</b> - For all Class I jobs involving the removal of more than 25 linear or 10 square feet of thermal system insulation or surfacing material; for all other Class I jobs, where the employer cannot produce a negative exposure assessment pursuant to paragraph (f)(2)(iii) of this section, or where employees are working in areas adjacent to the regulated area, while the Class I work is being performed, the employer shall use one of the following methods to ensure that airborne asbestos does not migrate from the regulated area.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(g)(5)(i)	<b>Asbestos</b> - For all Class I jobs involving the removal of more than 25 linear or 10 square feet of thermal system insulation or surfacing material; for all other Class I jobs, where the employer cannot produce a negative exposure assessment pursuant to paragraph (f)(2)(iii) of this section, or where employees are working in areas adjacent to the regulated area, while the Class I work is being performed, the employer shall use one of the following methods to ensure that airborne asbestos does not migrate from the regulated area.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000

OSHA Citation Tracking  
Serious Violations FY 2002

Installation	UIC	Inspection Date	Inspection Type	Violation Type	Standard Cited	Description	NAVOSH Reference	Abatement Date	Maximum Private Sector Penalty
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(j)(1)(i)	<b>Asbestos</b> - Decontamination areas: the employer shall establish a decontamination area that is adjacent and connected to the regulated area for the decontamination of such employees. The decontamination area shall consist of an equipment room, shower area, and clean room in series. The employer shall ensure that employees enter and exit the regulated area through the decontamination area.	OPNAVINST 5100.23F Chapter 11 Basic Requirements	2/5/2003	\$7,000
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(h)(1)(i)	<b>Asbestos</b> - Respiratory protection. (1) General. For employees who use respirators required by this section, the employer must provide respirators that comply with the requirements of this paragraph.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(f)(2)(i)	<b>Asbestos</b> - Initial Exposure Assessment. Each employer who has a workplace or work operation covered by this standard shall ensure that a "competent person" conducts an exposure assessment immediately before or at the initiation of the operation to ascertain expected exposures during that* operation or workplace. The assessment must be completed in time to comply with requirements which are triggered by exposure data or the lack of a "negative exposure assessment," and to provide information necessary to assure that all control systems planned are appropriate for that operation and will work properly.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000

OSHA Citation Tracking  
Serious Violations FY 2002

Installation	UIC	Inspection Date	Inspection Type	Violation Type	Standard Cited	Description	NAVOSH Reference	Abatement Date	Maximum Private Sector Penalty
					1926.1101(f)(3)(i)	<b>Asbestos</b> - Periodic monitoring. Class I and II operations. The employer shall conduct daily monitoring that is representative of the exposure of each employee who is assigned to work within a regulated area who is performing Class I or II work, unless the employer pursuant to (f)(2)(iii) of this section, has made a negative exposure assessment for the entire operation.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(k)(9)(i)	<b>Asbestos</b> - Employee Information and Training. (i) The employer shall, at no cost to the employee, institute a training program for all employees who are likely to be exposed in excess of a PEL and for all employees who perform Class I through IV asbestos operations, and shall ensure their participation in the program.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000
Naval Public Works Center, Great Lakes, IL	65113	6/18/2002	Complaint	Serious	1926.1101(i)(1)(i)	<b>Asbestos</b> - Protective clothing. General. The employer shall provide and require the use of protective clothing, such as coveralls or similar whole-body clothing, head coverings, gloves, and foot coverings for any employee exposed to airborne concentrations of asbestos that exceed the TWA and/or excursion limit prescribed in paragraph (c) of this section, or for which a required negative exposure assessment is not produced, or for any employee performing Class I operations which involve the removal of over 25 linear or 10 square feet of TSI or surfacing ACM and PACM.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000

OSHA Citation Tracking  
Serious Violations FY 2002

Installation	UIC	Inspection Date	Inspection Type	Violation Type	Standard Cited	Description	NAVOSH Reference	Abatement Date	Maximum Private Sector Penalty
					1926.1101(i)(3)	<b>Asbestos contaminated clothing.</b> Contaminated clothing shall be transported in sealed impermeable bags, or other closed, impermeable containers, and be labeled in accordance with paragraph (k) of this section.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 17 Asbestos Control	2/5/2003	\$7,000
U.S. Navy Millington, TN	66540	7/31/2002	Complaint	Serious	1910.305(g)(1)(i)	<b>Electrical wiring methods</b> -Flexible cords and cables-(1) Use of flexible cords and cables. (i) Flexible cords and cables shall be approved and suitable for conditions of use and location. Flexible cords and cables shall be used only for: Data processing cables approved as a part of the data processing system.	OPNAVINST 5100.23F Chapter 11 Basic Requirements	8/16/2002	\$7,000
U.S. Navy Millington, TN	66540	7/31/2002	Complaint	Serious	1910.303(b)(1)	<b>Electrical equipment.</b> Electrical equipment shall be free from recognized hazards that are likely to cause death or serious physical harm to employees. Suitability of equipment for an identified purpose may be evidenced by listing or labeling for that identified purpose.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 5 Prevention and Control of Workplace Hazards	8/16/2002	\$7,000
Naval Air Depot, Building 797 - Jacksonville, FL	00207	9/25/2002	Complaint	Serious	1910.212(a)(1)	<b>Types of guarding.</b> One or more methods of machine guarding shall be provided to protect the operator and other employees in the machine area from hazards such as those created by point of operation, ingoing nip points, rotating parts, flying chips and sparks. Examples of guarding methods are-barrier guards, two-hand tripping devices,electronic safety devices, etc.	OPNAVINST 5100.23F Chapter 11 Basic Requirements; Chapter 5 Prevention and Control of Workplace Hazards	2/28/2003	\$7,000



OSHA Citation Tracking  
Serious Violations FY 2002

Installation	UIC	Inspection Date	Inspection Type	Violation Type	Standard Cited	Description	NAVOSH Reference	Abatement Date	Maximum Private Sector Penalty
--------------	-----	-----------------	-----------------	----------------	----------------	-------------	------------------	----------------	--------------------------------

**Note:**

The abatement date is established by the OSHA area office. The period of time to abate a hazard is the shortest interval that an employer can reasonably be expected to correct the violation.

The OSHA Act authorizes civil penalties be assessed for each alleged violation. Most Federal agencies are exempt from these fines. Penalties are based on four factors: 1) the gravity of the violation: 2) the size of the business; 3) the good faith of the employer; 4) the employer's history of previous violations.